# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 9

ORDER

88-01

9 In The Matter Of:

10 POLY-CARB, INC.
WELLS, NEVADA

11

12 MONTANA REFINING COMPANY,

13 Respondent

14 PROCEEDING UNDER SECTION 106(a)
OF THE COMPREHENSIVE ENVIRONMENTAL
RESPONSE, COMPENSATION AND LIABILITY )
ACT OF 1980 (42 U.S.C. 9606(a))

3

6

7

8

16

17

#### I. JURISDICTION

The following Order is issued on this date to MONTANA

REFINING COMPANY ("Respondent") pursuant to Section 106(a) of

the Comprehensive Environmental Response, Compensation and Liability

Act of 1980 (CERCLA), 42 U.S.C. 9606(a) as amended by the Superfund

Amendments and Reauthorization Act of 1986 (SARA), Pub. L.

No. 99-499, by authority delegated to the undersigned by the

Administrator of the United States Environmental Protection

Agency ("EPA"). Notice of the issuance of this Order has

heretofore been given to the State of Nevada.

The Director, Toxics and Waste Management Division, EPA

The Director, Toxics and Waste Management Division, EPA 28 Region 9 has determined that there may be an imminent and

substantial endangerment to the public health or welfare or the environment because of an actual or threatened release of hazardous substances from a facility in Wells, Nevada formerly operated by Poly-Carb, Inc. Those hazardous substances were sent to the Poly-Carb, Inc. facility by Respondent.

This Order directs Respondent, Montana Refining Company to undertake actions to protect the public and the environment from this endangerment.

### II. FINDINGS OF FACT

# A. Background

- 1. On August 21, 1984 and September 26, 1984, Respondent sent shipments of phenolic caustic containing phenol and cresol to a purported waste conversion facility operated by Poly-Carb, inc ("Poly-Carb") in Wells, Nevada for treatment or disposal.
- 2. Poly-Carb, Inc's purported waste conversion facility site is located off US Highway 93 approximately one-half mile north of I-80 in Wells, Elko County, Nevada ("the facility").
- 3. Montana Refining Company is a limited partnership with its headquarters in Black Eagle, Montana.
- 4. On May 27, 1985 between 7200 and 9000 gallons of a solution containing phenol and cresol spilled from a holding tank at the facility and contaminated approximately 1500 cubic yards of soil adjacent to and under a building.
- 5. Between June 3-10, 1985, Poly-Carb excavated some of the contaminated soil and placed it in two trenches lined with visqueen plastic for temporary storage. The company collected samples of the contaminated soil. Analysis of these samples by the University of Nevada, Reno biochemistry department detected the following

concentrations of phenol and cresol in the samples:

Ì

Ą.

,

()

<u>phenol</u> <u>cresol</u> (<u>in ppm</u>)
oil layer <u>40,900</u> 36,200
soil 723 130

- 6. On June 7, 1985, Nevada Division of Environmental Protection ("DEP") issued Poly-Carb a "Finding of Alleged Violation" and "Order" charging Poly-Carb with operating a hazardous waste facility without a permit, illegal waste disposal, and unlawful discharge of a pollutant to ground water. The Order required Poly-Carb to submit an acceptable sampling plan and site security measures by June 21, 1985.
- 7. On July 12, 1985, DEP issued a "Finding of Alleged Violation, Proposed Stipulated Civil Penalty, and Order" after determining that Poly-Carb had failed to comply fully with the earlier order. This order required Poly-Carb to complete cleanup by August 14, 1985. Due to the inadequate response by Poly-Carb, the DEP requested EPA assistance in November of 1985.
- 8. On March 25, 1986, Poly-Carb filed for bankruptcy in Eugene, Oregon without implementing any further site mitigation activities.
- 9. In June of 1987, the EPA began clean-up of the contaminated soil on the basis of EPA Immediate Removal Action Memorandum Wells Site, Wells, NV dated May 14, 1987. At that time EPA had no information as to the identity of any potentially responsible party other than Poly-Carb, Inc and its principal Mike Wilwerding. In September of 1987, EPA learned that Respondent had sent hazardous materials to Poly-Carb. EPA has no information that any other person sent any hazardous materials to the facility.
  - 10. The EPA has designated an On-Scene Coordinator ("OSC")

3

ŗ,

6

8

()

11

12

14

15

17 18

19

20 21

22

24

26

27

28

1. Montana Refining Co. is a "person" as defined in Section

- 11. Phenol and cresol are toxic chemicals which have a wide range of health effects, varying from severe skin effects to systemic damage to the liver and kidneys. Phenol also affects mucous membranes and causes digestive disturbances. Phenol is a suspected co-carcinogen.
- 12. EPA has found to date approximately 1500 cubic yards of phenol and cresol-contaminated soil along with approximately 500 gallons of liquid containing phenol and cresol stored in abandoned tanks on-site. Phenol levels in the trench soil have ranged up to 2300 ppm and cresol levels have ranged up to 1480 ppm. A sample of residual material in one tank contained 18,000 ppm phenol and 14,000 ppm cresol. During the Preliminary Assessment of November 1986, EPA observed that the condition of the thin visqueen plastic lining the trench had deteriorated and was torn in several areas.
- 13. Phenol and cresol are both very mobile in alkaline soils which are found on-site. Shallow ground water occurs at 25 feet below the site. The phenol and crasol spilled onto the soil at the facility therefore, pose a subtantial threat to groundwater.
- There is also potential for humans to contact these contaminants in the soil and in the tanks. Both chemicals are extremely toxic through the dermal route of exposure.
- 15. Population at risk: The City of Wells relies entirely on ground water for its water supply. Both municipal wells are downgradient from the site.

# III. CONCLUSIONS OF LAW

- 2. The Poly-Carb, Inc. facility, located in "ells, Nevada is a "facility" as defined in Section 101(9) of CERCLA, 42 U.S.C. \$9601(9).
- 3. Montana Refining Company generated the phenolic caustic containing phenol and cresol and arranged for the transport of the phenolic caustic to the facility for treatment or disposal and is a "responsible" party as provided in Section 107(a)(3) of 9|| CERCLA, 42 U.S.C. \$9607(a)(3).
  - 4. Phenol and cresol are "hazardous substances" as defined in Section 101(14) of CERCLA, 42 U.S.C.
- There has been an actual "release", as defined in Section 13|| 101(22) of CERCLA, 42 U.S.C. §9601(22), of cresol and phenol into 14 the environment.

#### IV. DETERMINATIONS

Based upon the foregoing Findings of Fact and Conclusions of Law, the Director, Toxics and Waste Management Division, EPA Region 9 has made the following determinations:

- 1. The release and threatened release of hazardous substances and pollutants or contaminants from the facility may present an imminent and substantial endangerment to public health and welfare and the environment.
- In order to prevent or mitigate immediate and significant risk of harm to human health and the environment, it is necessary that removal action continue to be taken to contain and prevent the release and potential release of hazardous substances, pollutants or contaminants from the facility.
  - 3. The response measures ordered herein are consistent

2

10

11 121

15

17

16

18

19

201 21

2211 23

24

261

27

with the National Contingency Plan, 40 C.F.R. Part 300.

Respondent is responsible for conducting the actions ordered heroin, which are necessary to protect human health and the environment.

## v. ORDER

Based upon the foregoing Findings of Fact, Conclusions of Law and Determinations, Respondent is hereby ordered and directed to implement the following measures:

- 1. Within five (5) days of the effective date of this Order, Respondent shall submit to EPA a written proposal with a schedule for the removal of all drums of containing hazardous substances from the facility.
- Within five (5) days of EPA approval of the proposal for drum removal, Respondent shall begin implementation of the proposal. Respondent shall fully implement the drum removal proposal as approved by EPA within the time period set forth in the schedule.
- 3. Within fifteen (15) days of the effective date of this Order, Respondent shall submit to EPA a written plan ("O & M plan") for the operation and maintenance of the treatment process for the contaminated soil. At a minimum, the O & M plan shall include: (1) provisions for an operator to maintain the treatment process at least 20 hours per week, including but not limited to: irrigation of the site, maintenance of the plumbing integrity, the pumps and the treatment system and changing out the carbon filters as needed under the direction of the OSC; (2) site safety measures which meet EPA site safety requirments to protect on-site workers and the surrounding community; and (3) an implementation schedule.

10

12

11

1

2

3

4

5

6

7

8

13 14

15

16

17

18

19 20

21

22

23

24

25 26

27

S

10

11 12

13 14

15

16 17

18 19

20 21

22

25

24

26

- 4. Within five (5) days of EPA approval of the O & M plan, Respondent shall begin implementation of the plan. Respondent shall fully implement the O & M plan as approved by EF within the time period set forth in the schedule and under the direction of the OSC.
- 5. Within twenty (20) days of the effective date of this Order, Respondent shall submit to EPA a written plan ("monitoring plan") for the monitoring of the facility. At a minimum, the monitoring plan shall include: (1) monthly sampling and analysis of leachate, soil and groundwater; (2) quality assurance for all data generated by the monthly sampling and analysis program; (3) sampling and analysis methods to be carried out in accordance with EPA approved methods for hazardous waste testing in EPA SW 846, Test Methods for Evaluating Solid Waste US EPA 1986, 3rd Edition; and (4) an implementation schedule for the monitoring plan. monitoring plan shall be implemented until EPA determines that cleanup levels have been achieved.
- 6. Within five (5) days of EPA approval of the monitoring plan, Respondent shall begin implementation of the plan. Respondent shall fully implement the monitoring plan as approved by EPA in accordance with the schedule and under the direction of the OSC.
- Within thirty (30) days of the effective date of this Order, Respondent shall submit to EPA for approval a plan ("closure plan") for final site closure. At a minimum, the closure plan shall include site grading, site restoration, confirmatory soil testing and an implementation schedule for the final site closure. At a minimum, the confirmatory soil testing

shall address the following locations at the facility: (1) the spill area; (2) the area of excavation under the demolished office; (3) the treatment area; (4) the tank area; (5) the drum storage area and (6) any areas identified by the OSC as areas of potential contamination. Final site closure shall also include final disposal of all contaminated carbon filters and any other remaining contaminated soil or leachate or waste from the closure of the facility.

- 8. Within ten (10) days of notification by the EPA that the soil and leachate levels are below the levels designated by EPA, Respondent shall begin implementation of the cleanup plan. The OSC will inform the Respondent of the designated levels prior to the notification for implementation of closure. Respondent shall fully implement the final site closure plan as approved by EPA within the time period set forth in the schedule.
- 9. Within five (5) days of the effective date of this Order, the Respondent shall designate and provide EPA with the name and address of a project Coordinator whose responsibilities will be to receive all notices, comments, approvals and other communications from EPA to the Respondent.
- 10. Within thirty (30) days of each sampling event required in the monitoring plan, Respondent shall submit a report of the monitoring results to EPA and DEP. At a minimum the monitoring report shall include a summary of the data, the field logs, and the raw data.
- 11. Within thirty (30) days of completion of all the activities outlined above, Respondent shall submit to EPA a report describing the facility closure actions.

Respondent is further ordered as follows:

3

Ą

5

6

7

8

Q

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

#### VI. COMPLIANCE WITH APPLICABLE LAWS

In carrying out the terms of this Order, Respondent shall comply with all federal, state and local laws and regulations. All hazardous substances/wastes removed from the facility must be handled in accordance with Subtitle C and Subtitle D of the Resource Conservation and Recovery Act, 42 U.S.C. §6921 at seq, and the Nevada Revised Statutes Sections 400 at seq, and the regulations promulgated thereunder.

#### VII. SUBMITTALS

All submittals and notifications to EPA pursuant to this Order shall be made to:

Director, Toxics and Waste Management Division Environmental Protection Agency, Region 9 215 Fremont Street San Francisco. California 94105

Copies of all submittals and notifications shall be sent simultaneously to:

Allen Biaggi Nevada Division of Environental Protection 201 South Fall Street Carson City, Nevada 89710

All approvals and decisions of EPA made regarding such submittals and notifications shall be communicated to Respondent by the Director, Toxics and Waste Management Division, U.S. Environmental Protection Agency, Region 9 or his designee. EPA will consult with Nevada DEP to ensure that the plans submitted pursuant to this Order are consistent with state and local requirements. No informal advice, guidance, suggestions or comments by EPA regarding reports, plans, specifications, schedules or any

other writing shall be construed to relieve the Respondent of their obligation to obtain such formal approvals as may be required herein.

#### VIII. ACCESS

Respondent shall grant access to employees and authorized representatives of EPA and the Nevada Division of Environmental Protection to the facility. Nothing in this paragraph is intended to limit in any way the right of entry or inspection that EPA or other agency may otherwise have by operation of law.

#### TX. ON-SCENE COORDINATOR

EPA has appointed an On-Scene Coordinator (OSC) who has the authority vested in the "On-Scene Coordinator" by 40 C.F.R. Part 300, et seq., published at 42 Fed. Reg. 31180 (July 16, 1982). That authority includes, without limitation, the right to: be on-site at all reasonable times; observe, take photographs and make other reports on the progress of the work as the OSC deems appropriate; and review records, files and documents relevant to the Order.

#### X. ENDANGERMENT DURING IMPLEMENTATION

In the event that the Director, Toxics and Waste Management Division, EPA, Region 9 determines that any activities (whether pursued in implementation of or in noncompliance with this Order) or circumstances are endangering the health and welfare of people on the site or in the surrounding area or to the environment, the Director may order the Respondent to stop further implementation of this Order for such period of time as needed to abate the endangerment.

3 3

# XI. GOVERNMENT LIABILITIES

The United States Government shall not be liable for any injuries or damages to persons or property resulting from the acts or omissions of the Respondent, its employee, agents or contractors in carrying out activities pursuant to this Order, nor shall the Federal Government be held as a party to any contract entered into by the Respondent, or its agents in carrying out activities pursuant to this Order.

# XII. PENALTIES FOR NONCOMPLIANCE

A willful violation or failure or refusal to comply with this Order, or any portion thereof, may subject you to a civil penalty of not more than \$25,000 per each day in which a violation occurs or such failure to comply continues, pursuant to the provisions of Section 106(b)(1) of CERCLA, 42 U.S.C. \$9606(b)(1). Failure to comply with this Order, without sufficient cause, may also subject you to punitive damages in an amount up to three times the total of all costs incurred by the Government as a result of your failure to take proper action, pursuant to the provisions of Section 107(c)(3) of CERCLA, 42 U.S.C. \$9607(c)(3).

EPA may take over the removal action at any time if EPA determines that Respondent is not taking appropriate action to mitigate the site hazard. In the event EPA assumes responsibility for the removal action, Respondent shall be liable for all costs incurred by EPA to mitigate the site hazard. EPA may order additional removal or remedial actions deemed necessary by EPA to protect the public health and welfare or the environment.

# XIII. OPPORTUNITY TO CONFER

You may request a conference with the Director, Toxics and

Waste Management Division, EPA Region 9 or his staff to discuss the provisions of this Order. At any conference held pursuant to your request, you may appear in person or by council or other representatives for the purpose of presenting any objections, defenses or contentions which you may have regarding this Order. If you desire such a conference, you must make such request orally within 24 hours of receipt of this Order, to be immediately confirmed in a written request. Please make any such request to either of the contact persons listed below.

## XIV. PARTIES BOUND

This Order shall apply to and be binding upon the Respondent, its officers, directors, agents, employees, contractors, successors and assigns.

# XV. NOTICE OF INTENT TO COMPLY

Immediately upon receipt of this Order, Respondent shall orally inform EPA of its intent to comply with the terms of this Order. This shall be confirmed in writing within two (2) days of receipt of this Order. Failure to notify EPA of the Respondent's intent to comply will be construed by EPA as a refusal to comply.

# XVI. EFFECTIVE DATE

Notwithstanding any conferences requested pursuant to the provisions of this Order, this Order is effective upon receipt, and all times for performance shall be calculated from that date.

25 ///

26 1//

ĭ

27 ///

28 ///

UNITED STATES ENVIRONMENTAL PROTECTION ICENCY 4 5 6 ACTING DIRECTOR, TOXICS & WASTE MANAGEMENT DIVISION EPA, REGION 9 7 8 () Contacts 10 Bob Mandel 11 Field Operations Branch T-3-3 US Environmental Protection Agency 215 Fremont Street San Francisco, CA 94105 (415) 974-8927 14 Julia Bussey 15 Superfund Programs Branch T-4-4 US Environmental Protection Agency 16 215 Fremont Street San Francisco, CA 94105 17 (415) 974-8228 18 Mike Hingerty 19 Assistant Regional Counsel Office of Regional Counsel 20 US Environmental Protection Agency 215 Fremont Street San Francisco, CA 94105 (415) 974-8636 22 23 24 25

26

27

28

It is so ordered on this 18th day of November, 1987.